## **Ideal Inspection**

(a division of Ideal Oilfield Construction Ltd.) P.O Box 1473 Brooks, Alberta TIR 1C3

## INSPECTION REPORT

Phone: 403-362-2843

Fax: 403-362-2862

Client: Four Star Ventures

Location: DaPaJo Construction Limited

Date: April 05, 2012

P.O. :

Work Order: 2139a

Report: 3471

Page: 1 of

Rig or Unit :#7 A

Inspection: Magnetic Particle

Parts Examined: 7" ACT 65 Ton elevator

S/N: 70872MA

Surface Condition: Painted

Material Temperature: 20° Celsius Code: ASME Section V, ASTM E709

Procedure: MPI-DPJ-001


Equipment: Parker B 310 Contour Probe, PM-50 Permanent Magnets Method: Magnetic Particle, AC Continuous, Wet Colour Contrast Method

Test Medium: Magnaflux 7HF prepared bath

Test Results:


Engineer's Approval:

No defects found at time of inspection



Signatur

The Association of Professional Engineers, Geologists and Geophysicists of Alberta



Photos:

Technician: John Frances			CGSB #:	7062	Signature:	Assistant:	Tyler Nevison
Repairs Complete	Yes	No	N/A X		The second secon	Acceptable For S	