Ideal Inspection(a division of Ideal Oilfield Construction Ltd.)
P.O Box 1473 Brooks, Alberta T1R 1C3

INSPECTION REPORT

Phone: 403-362-2843

Fax: 403-362-2862

Client: 4 Star Ventures	Location: DaPaJo Construction Limited		Date: October 21, 2014
Page: 1 of 1	Unit :62440		
Work Order:2520C	Report: 4269		Inspection: Magnetic Particle
Parts Examined: 9 5/8" Web Wilson Casing Elevator			
Surface Condition: Painted Material Temperature: 18° Celsius			
Procedure: MPI-DPJ-001		Code: ASME Section V, ASTM E709	
Equipment: Parker B 310 Contour Probe, PM-50 Permanent Magnets			
Method: Magnetic Particle, AC Continuous, Wet Colour Contrast Method			
Test Medium: Magnaglo 14AM prepared bath			
Test Results:			
No cracks found at time of inspection			
The state of the s			
Photos:			
ARTICLE STATE OF THE PARTY OF T			
- 12		(Address of the control of the cont	
			The state of the s
			The state of the s
			Activities
THE CONTRACT AND ADDRESS AND A			
Technician: Bryan Hoskins CGSI	24. 1 400.00		
E MANUFACTURE AND	B #: 19053	Signature: 3	Assistant: Travis Bungay
Repairs Complete Yes No N/A	X	The second secon	Acceptable For Service Yes X No
Acceptable For Service Yes X No			